

TREE #	ADDRESS (W. Green St.)	INVENTORY SITE NUMBER	ID #	REASON FOR REMOVAL	MIKE BRUNK'S NOTES	KEVIN/ DAVEY INVENTORY NOTES	ADDITIONAL NOTES
1	802	#2	13605	Tree condition and Bus Stop/ADA	(no comments)	Cabled system installed, potential of failure evident	Bad crotch south side with included bark, potential failure, weeping. Very soft root flare south side, hollow sounded with hammer
2	802	#1	722	Tree condition and Bus Stop/ADA	Bad shape/declining tree	Location , poor condition (2013), continued maintenance issues	Major decline, trunk completely hollow, very limited holding wood. Failure high risk
3	712	#1	4116	Species and tree condition	Bad tree	Fair condition (2013); species (Elm) susceptible to disease (wetwood) and ice storm	Elm is ice storm/wind storm susceptible, major lean over street, encroaching on resident nice Buckeye (better species)
4	702	#1	17611	Tree condition	Declining tree	Location , poor condition (2013), continued deadwood issue	Fruiting bodies at root flare, failure waiting. Major trunk damage, trunk sounds hollow with sounding hammer
5	609	#1	352	Tree condition	Declining tree/fungus up top	Fair condition (2013), poor structure	Bad trunk, wound/cavity east side
6	601	#1	10521	Tree condition and Bus Stop/ADA; trade-off to save other tree	Can sidewalk be sawed so tree isn't impacted?	Location , fair condition (2013)	Root system will take major damage thru construction
7	508	??		Tree condition	Tree not in good shape	(no comments)	Dieback in canopy, cavity in center lead from loss of top, poor structure
8	503	#1	5180	Tree condition	Remove declining tree/ Dead at Top	Fair condition (2013)	Should be listed as poor condition, cavity at root flare, hazard
9	501	#1 SA	5922	Tree condition and grading/ADA; proximity to sidewalk	Tree has Bees in it. Try to save Sugar Maple. Ramps could be a concern.	(no comments)	Honey Bee in hollow 15' east side, trunk hollow sounding hammer. Poor location to existing sidewalk
10	411	#1	8842	Species and tree condition	Has some issues (rot)	Norway Maple, major structure issues, major limb falls, falling apart, bad location	Cavity at base and both leads, bad crotch, leads in canopy split lost branches, multiple limb falls from past storms.
11	403	#1	1182	Tree condition	Bad tree	Siberian Elm	Bacterial wetwood within tree, slime flux seeping down tree. Dead wood
12	401	#1	5944	Tree condition and Bus Stop/ADA	In bus stop	Cavity/Decay, hazard rating of 7	Stressed, small leaves, top dieback
13	401	#2	6032	Tree condition and Bus Stop/ADA	Bad tree - has some rot	Location , poor condition (2013), cavity/decay, hazard rating of 7	Trunk hollow, sounded with hammer, major cavities at trunk, top dieback
14	404		1172	Tree condition	Bad Shape	Location , poor condition (2013), cavity/decay, hazard rating of 6	Cavity at trunk, trunk sounds hollow with sounding hammer
15	306	#1	399	Unable to obtain easement	Possible Conflict with Business Sign (Easement)	(no comments)	
16	303		932	Tree condition	Tree has rot	(no comments)	
17	301		914	Unable to obtain easement	Can sidewalk be shifted to south? Fair Sugar Maple	(no comments)	Estimate 5years remaining life with die-back
18	302	#1	2166	Tree condition and grading/ADA	(no comments)	Location	Interior fungus, fruiting bodies on exterior. Dead wood in canopy
19	208	#1	13477	Change in curb location due to intersection design change. Narrowed sidewalk to save 2 adjacent trees	Can this tree be saved? Watch curb shift to north.	Library Lot	